



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor


# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

Division of Oil, Gas and Mining  
JOHN R. BAZA  
Division Director

### Minerals Inspection Report

Reviewed 


Report Date: 04/24/2014

Mine Name: Treasure Chest	Permit Number: S/023/0028	Mine Status: Active
Operator Name: The Bug House	Inspection Date: 04/09/2014	Permit Fees: Paid
Inspector(s): Wayne Western	Inspection Time: 4:00 - 4:30 PM	Bond Amount: \$12,371
Attendee(s): Duane Bays	Weather: partly cloudy sky	Bond Escalation: 06/18/2016
Inspection Purpose: Routine inspection		Prior Inspection: 08/23/2012

#### Conclusions and Recommendations

There were several groups at the site that were digging for geodes without permission. The work was done by hand and the disturbance caused was minimal. The site is stable.

Elements of Inspection		Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Bond and permit fees current		
2.	Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	People routinely visit the site to rock hound. The site is shown as a rock hounding area on several maps. Signs have been placed to prevent trespassing.		
3.	Protection of Drainages/Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	No signs of erosion.		
4.	Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>
5.	Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>
6.	Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8.	Soils	<input type="checkbox"/>	<input type="checkbox"/>
9.	Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10.	Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC: Duane Bays BLM

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M023-Juab/S0230028-treasurechest/inspections/INSP04092014.pdf





Overburden



Overburden and working area



Disturbed area on left undisturbed on right



Excavator left on site